



JON M. HUNTSMAN, JR.
Governor

GARY R. HERBERT
Lieutenant Governor

State of Utah

DEPARTMENT OF NATURAL RESOURCES

Division of Oil, Gas & Mining

MICHAEL R. STYLER
Executive Director

JOHN R. BAZA
Division Director

Inspection Report

Minerals Regulatory Program

December 23, 2008

Reviewed: 

Mine Name: Corner Creek Project	Permit number: E/003/0037
Operator Name: Black Rose Minerals, Inc	Inspection Date: October 15, 2008
Inspector(s): Lynn Kunzler	Time: 9:00 am
Other Participants: Drilling Crew	Mine Status: Active

Elements of Inspection	Evaluated	Comment	Enforcement
1. Permits, Revisions, Transfer, Bonds	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
2. Public Safety (shafts, adits, trash, signs, highwalls)	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
3. Protection of Drainages / Erosion Control	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4. Deleterious Material	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
5. Roads (maintenance, surfacing, dust control, safety)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
6. Concurrent Reclamation	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
7. Backfilling/Grading (trenches, pits, roads, highwalls,	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
8. Soils	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
9. Revegetation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
10. Other	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

Purpose of Inspection:

Routine inspection while in the area.


Inspection Summary:

The operator has completed the first phase of drilling and submitted an amendment to drill additional holes. Upon arrival at the site, the second drilling company was setting up preparing to drill. Holes from the first drilling were examined and found to be adequately plugged, except one hole which was producing water. The land owner has requested that this hole be left open and is in the process of applying for the water right to use this water for his ranching operation.

The site was stable and free of debris. There were no erosion problems noted.

Conclusions and Recommendations:

Continue to monitor the site when in the area.

Inspector's Signature 

LK:vs

cc: Steve Ewell, Operator

O:\M003-BoxElder\E0030037-CornerCreek\inspections\insp-10152008.doc